

Case Study Pico Wastewater Treatment

การบำบัดสิ่งแวดล้อม

SOLID & LIQUID SEWAGE TREATMENT IN CHINA



Waste water treatment



Eliminate waste water smell
Eliminate blue green algae

Reduce electricity consumption
and pump maintenance

Case Study of Animal Farm in Eastern China



成功的应用实例

养猪场废水氧化塘的处理 - 位于南中国的广东

The condition of the Main Pond waste-water before treatment was covered with grease, oils, solids and smelly.



前的状况 - 摄于 30/12/2003

Significant reduction in grease, oils, solids and odour was not observed after 3 weeks.



一个月之后的状况 - 摄于 29/01/2004 ⁶²

Algae Control – GuangDong China



投放“清绿净”之前

Before Inoculation



投放三周后

Three weeks later

WASTEWATER TREATMENT

Before

After



Thick Sludge with pathogenic bacteria **Digest Sludge, reduce BOD & COD**